

# SEE PAGE 13 FOR IMPORTANT INFORMATION CONCERNING LIMITED WARRANTY, AND LIMITATION OF LIABILITY.

#### INTRODUCTION

The Bergen BM Series Safety Cable application tool is designed to terminate ferrules to Safety Cable in accordance with SAE specification AS4536\*. The application tool installs Safety Cable kits identified in SAE specifications AS3509\*, AS3510\*, AS3511\*, and AS3655\*. The following steps are important to assure proper Safety Cable applications:

- 1. Proper cable installation (section 1.0)
- 2. Proper loading and use of the application tool (section 2.0)
- 3. Verification of proper installation (section 3.0)
- 4. Tool maintenance and calibration (section 4.0)

\* SAE publications are available from:

SAE, International 400 Commonwealth Drive Warrendale, PA 15096-0001 U.S.A.

#### 1.0 PROPER CABLE INSTALLATION

1.1 Various examples of Safety Cable installation are shown in Figs. 1 thru 3.

Although all possible combinations are not shown, three basic rules apply:

A) It is recommended that Safety Cable be installed in such a manner that any tendency for a fastener to loosen will be counteracted by an additional tension on the cable. Sharp turns in excess of 135° should be avoided. Installed Safety Cable should produce a positive or neutral pull on the fastener.

B) Safety Cable should be installed in two or three bolt patterns. Two bolt patterns are preferred when Safety Cable is applied to an even number of fasteners.

C) Maximum span of Safety Cable shall be six inches from end to end.









#### 2.0 PROPER LOADING AND USE OF THE APPLICATION TOOL

- 2.1 Select the proper size & length of Safety Cable.
- 2.2 Install the Safety Cable through the fasteners as described in section 1.0.
- 2.3 The nose of the tool can be rotated to any position (see Fig. 4). Rotate the tool nose to the desired position.
- 2.4 Insert the free end of the cable through the ferrule as shown in Fig. 5 and pull out the ferrule from the magazine.
- 2.5 Insert the free end of the cable through the nose as shown in Fig. 6. Slide the tool along the cable to the desired position. Make certain that the ferrule is fully seated in the nose.
- 2.6 Position the tool nose such that the ferrule is pressed squarely against the fastener. Hold the tool nose steady and perpendicular to the fastener.

CAUTION: DO NOT RELEASE THE FREE END OF THE CABLE UNTIL IT HAS BEEN INSERTED THROUGH THE NOSE.

SCTBR-DS
----------

©2010 ALL RIGHTS RESERVED Page 2 of 13

REV. A









- 2.7 Wrap the free end of the cable into the cable entrance as shown in Fig. 7. Wrap the cable one full revolution around the tensioning wheel making sure the cable is held in place by the wheel. Tension the cable by rotating the wheel clockwise until several distinct clicks are heard.
- 2.8 Hold the tool nose steady and perpendicular to the fastener to maintain consistent cable tension. Completely close the handles to crimp and cut the cable.
- 2.9 After crimping and cutting, release the tool handle and slide the tool off the crimped ferrule. Pull the excess cable from the tool, by unwinding in the counterclockwise direction. Dispose of the cut cable properly.
- 3.0 VERIFICATION OF INSTALLATION
- 3.1 Verify proper tension of the cable. Refer to Table 1, Fig. 8 for Safety Cable flex limits. (Not applicable for .062 diameter cable.)
- 3.2 Verify that the cable was installed through the fasteners in accordance with section 1.0.
- 3.3 Verify that the cable was cut flush at the end of the ferrule with no strand extending more than 1/32 inch from the end of the ferrule.
- 3.4 Visually inspect the cable for any nicks or other damage that may have occurred during installation.

BERGEN CABLE TECHNOLOGY, LLC

DATASHFF



TABLE 1	FLEX LIMITS, DIMENSIONS		
А	В	С	
in. (mm)	in. (mm)	in. (mm)	
0.5 (12.7)	0.125 (3.18)	0.062 (1.59)	
1.0 (25.4)	0.250 (6.35)	0.125 (3.18)	
2.0 (50.8)	0.375 (9.52)	0.188 (4.76)	
3.0 (76.2)	0.375 (9.52)	0.188 (4.76)	
4.0 (101.6)	0.500 (12.70)	0.250 (6.35)	
5.0 (127.0)	0.500 (12.70)	0.250 (6.35)	
6.0 (152.4)	0.625 (15.88)	0.312 (7.94)	



### 4.0 <u>TOOL MAINTENANCE AND CALIBRATION:</u> The following procedure is recommended for proper care and maintenance of the BM series tools, to achieve a good installation of the Safety Cable.

#### 4.1 Maintenance of the Crimp Cavity: FERRULES CAN STICK OR JAM INSIDE THE CRIMP CAVITY IF THIS PROCEDURE IS NOT FOLLOWED.

- 4.1.1 During normal usage of the tool, dirt and debris can accumulate in the crimp cavity.
- 4.1.2 The accumulated debris must be cleaned periodically by brushing or scraping the crimp cavity. After cleaning, blow air to remove any debris still sticking.



- 4.1.3 After the cavity is thoroughly cleaned, apply a thin film of lightweight synthetic or petroleum based oil.
- 4.1.4 The tool must be checked at regular intervals. The actual period between the checks depend on the number of crimps made with the concerned tool. The frequency of check, cleaning and applying of oil should be established by local Manufacturing Engineering, end users or installers depending on their practice and environment. Checking the crimp done by each tool at the beginning, middle and end of each shift is considered as a good practice to ensure proper installation of the safety cable.
- 4.2. Adjusting Cable Tension:
- 4.2.1 The cable tension may be adjusted using a 1/4" straight screw driver. Turn the tension adjustment screw (see figure 9) clockwise to increase cable tension or counterclockwise to decrease the cable tension. See Table 1 for allowable flex limits.

DO NOT OVER ADJUST THE CABLE TENSION.





- 4.3. Tensioning Wheel Location: As shipped the tensioning wheel is always mounted on the right side, but may be mounted on the left side at field if required.
- 4.3.1 Remove the retaining ring shown in figure 10, using proper retaining ring pliers. (Do not remove the retaining ring on the tension wheel).



4.3.2 Gently pull out the tensioning wheel and spacer from the tool. Install the spacer and tensioning wheel on the other side of the tool. Align the notch in the spacer with the pin in the tool body and reinstall the retaining ring (see figure 11).





#### 4.4. Indentor Adjustment:

CAUTION: We strongly recommend that the indentor adjustment or tool nose replacement must be done by a trained and experienced mechanic.

Always verify tool calibration in accordance with Section 4.5 each time the tool nose is removed, adjusted or installed.

Tightening the crimp increases required hand forces during application and increases cable assembly tensile values. Loosening the crimp decreases required hand forces during the application and decreases cable assembly tensile values. Over adjustment may permanently damage the tool crimping mechanism.

Remove the nose assembly by removing the two security bit screws as shown in Figure 12. 4.4.1



Unlock the jam nut using the special spanner wrench SCT32084, and adjust the pushrod 4.4.2 adjustment screw using a <sup>1</sup>/<sub>4</sub>" straight edge screwdriver (see figure 13). Turn the pushrod adjustment screw clockwise to loosen the crimp. Turn the adjustment screw counterclockwise to tighten the crimp. After each adjustment securely tighten the jam screw (while holding the adjustment screw stationary with the screwdriver) prior to the installation of the nose assembly.

343 Kaplan Dr, Fairfield, NJ 07004 USA Phone: 973-276-9596 Fax: 973-276-9566 Email: Sales@BergenCable.com

REV. A

©2010 ALL RIGHTS RESERVED



4.4.3 Replace the nose assembly and the two special socket head cap screws. Prevent binding by alternately turning each screw a small amount until tight.

Check calibration as described in Section 4.5.

4.5. Checking of the Tool Crimp System Using Test Block TB-201:

©2010 ALL RIGHTS RESERVED

4.5.1 Thread the cable into the left swivel and through the right swivel, holding the lever in the home position as show in Figure 14. If the lever is not kept in the home position the results may be adversely affected. Terminate the cable per Section 2.0, making sure to close the handles completely.



4.5.2 Apply approximately 2 LB force to the cable with your finger at the line marked "TEST AREA". If the cable touches either the side or bottom surface of the test area then remove the cable from the test block and adjust the cable tension per Section 4.2. Terminate another cable as described above, making sure that the tool nose is perpendicular to the fastener as shown in Figure 6. Repeat this procedure until the cable does not touch either the side or bottom surfaces of the test area.

Bergen Cable Technology, LLC 343 Kaplan Dr, Fairfield, NJ 07004 USA

Phone: 973-276-9596 Fax: 973-276-9566 Email: Sales@BergenCable.com

Page 9 of 13

REV. A

BERGEN CABLE

DATASHEE

- BERGEN CABLE TECHNOLOGY, LLC DATASHEET
- 4.5.3 Place a calibrated 3/8" drive inch-pound torque wrench into the square drive hole, orienting the test block and torque wrench on a flat surface as shown in Figure 15. Apply the proper pull-off load as shown in Table 2. Release torque when minimum pull-off load is achieved. Do not apply additional tension to the cable.



- 4.5.4 If the cable did not break or pull out of the ferrule after applying proper torque, remove the torque wrench and apply approximately 2lb force to the cable with your finger at the line marked "TEST AREA". If the cable does not touch the side or bottom surface of the test area, the crimp is acceptable.
- 4.5.6 If the cable breaks or pulls out of the ferrule, then the crimp is unacceptable and the tool indenter should be adjusted. If the cable touches either the side or bottom surface of the test area, then the crimp is unacceptable and the tool indenter should be adjusted per section 4.4.



Bergen Safety Cable kit includes one cable with an end fitting attached and a ferrule. Kits are packaged and sold in lots of 50; the ferrules are loaded in a spring loaded magazine. Following are the kit part numbers.

TABLE 202	TABLE 2022, .032, .040 NOMINAL DIAMETER CABLE KITS			Minimum Pull-Off
Kit Part	(D) Cable	Component Material	(L) Length	Load-Lbf (Nm) or
Number	Diameter	_	(Inches)	Torque-Lb.In
K20B06			6	
K20B09		UNS S32100	9	
K20B12	.022026	CORROSION	12	
K20B15	(1x7 Cable)	AND HEAT	15	30 (3.4)
K20B18		RESISTANT	18	
K20B21		ALLOY (AMS5689)	21	
K20B24			24	
K30B06			6	
K30B09		UNS S32100	9	
K30B12	.032038	CORROSION	12	
K30B15	(3x7 Cable)	AND HEAT	15	70 (7.9)
K30B18		RESISTANT	18	
K30B21		ALLOY (AMS5689)	21	
K30B24			24	
K40B06			6	
K40B09		UNS S32100	9	
K40B12	.040046	CORROSION	12	
K40B15	(7x7 Cable)	AND HEAT	15	110 (12.5)
K40B18		RESISTANT	18	
K40B21		ALLOY (AMS5689)	21	
K40B24			24	

NOTE: Letter "B" in the kit part number represents UNS S32100 Stainless Steel material. See "Bergen Cable Part Number" chart on page 12 for the letter codes of other materials.



Bergen Cable Technology offers complete refurbishing and recalibration services.

BERGEN CABLE TECHNOLOGY, LLC

DATASHEET



#### **INVALIDATION OF LIMITED WARRANTY**

THIS MANUAL IS PROVIDED TO THOSE OWNERS OF BERGEN CABLE TECHNOLOGY, LLC (BERGEN) PRODUCTS WHO HAVE ELECTED TO CONDUCT IN-HOUSE REPAIRS OF SUCH PRODUCTS AND WHO THEREBY CONSENT TO WAIVE ANY RIGHTS WHICH THEY OTHERWISE MIGHT HAVE HAD UNDER THE BERGEN LIMITED WARRANTY APPLICABLE TO SUCH PRODUCTS.

BERGEN PROVIDES COMPLETE REPAIR AND MAINTENANCE SERVICE FOR ALL OF ITS PRODUCTS. OWNERS OF BERGEN PRODUCTS ARE WARNED THAT ANY TAMPERING, INCLUDING PARTIAL OR COMPLETE DISASSEMBLY OF THE PRODUCT OR ATTEMPTED REPAIRS OF THE PRODUCT WILL INVALIDATE THE LIMITED WARRANTY APPLICABLE TO SAID PRODUCT.

#### **LIMITATION OF LIABILITY**

BERGEN CABLE TECHNOLOGY, LLC (BERGEN) IS NOT LIABLE FOR CONSEQUENTIAL OR SPECIAL DAMAGES OF ANY NATURE OR KIND RESULTING FROM THE USE, OR MISUSE, OF ANY OF ITS PRODUCTS. OWNERS AND USERS OF BERGEN PRODUCTS ASSUME FULL RESPONSIBILITY FOR INSTRUCTING THEIR EMPLOYEES IN THE PROPER AND SAFE USE OF SUCH PRODUCTS.

#### **LIMITED WARRANTY**

Bergen (Bergen Cable Technology, LLC) warrants each new product sold by it to be free from defects in material and workmanship under normal use and service. Bergen's obligation under this warranty is limited to the free correction or, at Bergen's option, the refund of the purchase price of any such product which proves defective in normal service within ninety (90) days after delivery to the first user, provided that the product is returned to Bergen with all transportation charges prepaid and which shall appear to Bergen's satisfaction, after Bergen's inspection, to have been defective in material or workmanship, it being understood that Bergen products are not consumer products. This warranty shall not cover any damage to any product which, in the opinion of Bergen, was caused by normal wear, misuse, improper operation, tampering, neglect or accident. This warranty is in lieu of all other warranties express or implied. No warranty, express or implied, is made or authorized to be mode or assumed with respect to products of Bergen Cable Technology, LLC other than those herein set forth.